




2011 DURANGO



DOOR ENTRY SILL



FRONT DOORSILLS



REAR DOORSILLS



1





97°F
35°C

52°F
15°C




2




FRONT

3 2X





4 2X

COMPLETELY REMOVE THE BACKING (LINER) OF THE TAPE.




5 2X




REAR

6 2X



7 2X

COMPLETELY REMOVE THE BACKING (LINER) OF THE TAPE.



8 2X